

# Xerus Firmware Release Notes



---

**Version:** Xerus 4.2.20 / Build 50793 / Release Notes, Version 1

**Release Status:** Limited Availability (LA)

**Date:** October 25, 2024

---

## Release Overview

Xerus 4.2.20 Firmware is an **incremental Limited Availability (LA) Release** for select Xerus-based product groups. This release may include performance and productivity improvements, support for new products and accessories, new features and enhancements, bug fixes, and general fixes for specific model families.

## Applicability

This firmware release applies to the following Xerus-based product brands and models.

<i>Product Group</i>	<i>Model</i>
Rack PDUs	PRO3X, DC PDU
Access Control	SmartLock™
Sensors	DX2 SmartSensors™
Asset Management	AMS2

## General Guidelines for this Release

This release may not support some custom-engineered models. Please check the **Support & Compatibility** section below. Or contact your regional Server Technology Support team if you are unsure of the model number of your unit—it is typically viewable from the GUI's *Device Information* page and is also printed on a label located on the device.

*Note:* Do NOT upgrade ANY other Server Technology model(s) to Xerus 4.2.20 Firmware (other than what is listed in the Applicability table above) because the unit may either not be compatible with Xerus Firmware or may have been built after this release entered our System Tests and installing it may result in the unit becoming non-functional.

*Note:* Do NOT downgrade your new Xerus-based product(s) to any prior Xerus Firmware release. Due to significant internal enhancements in Xerus 4.2.20, a downgrade from Release 4.2.20 Build 50793 to ANY prior firmware release is NOT SUPPORTED. Please contact your regional Server Technology Support team with any questions.

## Release Highlights

### New Features & Enhancements

<i>Issue ID</i>	<i>Description</i>
<b>83608</b>	Raising required minimum firmware versions
<b>84306</b>	SmartLock - Two RFID card authentication support. Two unique cards can be required for authentication to gain physical access to a rack

### Bug Fixes

<i>Issue ID</i>	<i>Description</i>
<b>83863</b>	Fixed missing links with JSON-RPC

### Security Fixes & Updates

<i>Issue ID</i>	<i>Description</i>
<b>83804</b>	Addressed WPA PEAP authentication bypass vulnerability (CVE-2023-52160)
<b>84054</b>	Addressed RADIUS MD5 collision vulnerability (CVE-2024-3596; Blast-RADIUS)

Please consult the appropriate User Guide for more information on these firmware features at [servertech.com/support](https://servertech.com/support).

## Support & Compatibility with Xerus 4.2.20

Except for some recent Engineered to Order (ETO) models, applicable Xerus-based units/models can be upgraded to this firmware release (see Applicability table above).

### Models Not Supported

This firmware release does not support the following Server Technology models:

- PRO2 models
- PRO1 models
- Sentry CDU models
- EMCU, EMTH, and EMWS Modules and Sensors

Please contact your regional Server Technology Support team if you are unsure whether this Xerus Firmware release supports your unit/model or have questions about supported or unsupported configurations.

## Upgrade Matrix (Path for Upgrades)

This firmware release is intended for factory shipments and firmware upgrades on the units/models stated in the Applicability table above.

*Note:* Due to file system changes in Xerus 4.0.x, the following upgrade paths must be followed, or the Xerus-based device may become inoperable and require manual recovery.

<i>If Current Firmware Version Is</i>	<i>Follow These Upgrade Steps</i>
<b>3.6.x</b>	» 4.2.0 » 4.2.20
<b>4.0.x, 4.1.x</b>	» 4.2.0 » 4.2.20
<b>4.2.x</b>	» 4.2.20

**Note:** Due to an issue found in recently released Xerus 4.0.x firmware updates, we strongly recommend upgrading to 4.2.20 Build 50793. If you need assistance, please contact your regional Server Technology Support team.

## Downloads

The following supplemental files can be downloaded at [servertech.com/support/rack-pdu-firmware-downloads](http://servertech.com/support/rack-pdu-firmware-downloads):

- PRO3X 4.2.20 Release Notes
- PRO3X User Guide
- PRO3X User Guide - SNMP MIB
- PRO3X Quick Start Guide

Historical firmware version downloads can be found on [servertech.com/support/rack-pdu-firmware-downloads](http://servertech.com/support/rack-pdu-firmware-downloads).

## Release Package Details

The Xerus 4.2.20 Firmware is a Limited Availability release, and firmware binary files are unavailable for public download through the Raritan support website. If this Xerus Firmware release applies to your specific model(s) and/or use case(s), please contact your regional Server Technology Support team for assistance. The team will ensure proper compatibility with your specific model(s) and provide applicable firmware files as needed.

## Xerus 4.2.20 Package

- "Xerus\_ReleaseNotes\_4.2.20.pdf" (this file)

## General Upgrade Instructions *(stand-alone upgrade from the browser-based user interface)*

- Enable JavaScript in your browser before logging into the unit to start the upgrade process.
- Follow the instructions in the proper device User Guide. Please read all upgrade instructions before starting an upgrade.

If you have questions or cannot follow the instructions in the User Guide, please STOP and contact Server Technology Support for further instructions.

## Contact Us

Go to [servertech.com/support](http://servertech.com/support) for contact options.

©2024 Legrand®. All Rights Reserved. Trademarks are the property of their respective owners. The industry-leading brands of Ortronics, Raritan, Server Technology, and Starline empower Legrand's Data, Power & Control to produce innovative solutions for data centers, building networks, and facility infrastructures. Our division designs, manufactures, and markets world-class products for a more productive and sustainable future. The exceptional reliability of our technologies results from decades of proven performance and dedication to research and development.