Xerus Firmware Release Notes

Server Technology
A brand of legrand®

Version:	Xerus 4.3.10 / Build 51837
Release Status:	General Availability (GA)
Date:	August 08, 2025

Xerus 4.3.10 Firmware is a GA Release and may include performance and productivity improvements, support for new products and accessories, new features and enhancements, bug fixes, and general fixes for specific model families.

Applicability

This firmware release applies to the following product groups and models:

Product Group	Model
Server Technology® Rack PDUs	PRO4X
Legrand® Access Control	SML SmartLock™
Legrand Sensors	DX2 SmartSensors™
Legrand Asset Management	AMS2 Strips

This firmware release does not support Server Technology PRO1, PRO2, Sentry CDU, EMCU, EMTH, or EMWS models.

Upgrade Path

This firmware release is intended for factory shipments and firmware upgrades on the units/models stated in the Applicability table above; if you are unsure of the model number of your unit—it is typically viewable from the GUI's *Device Information* page and is also printed on a label located on the device. (This release may not support some custom-engineered models.)

The release package for this firmware update is available at servertech.com/support/rack-pdu-firmware-downloads.

Due to file system changes in Xerus 4.0.x, the following upgrade paths must be followed, or the Xerus-based device may become inoperable and require manual recovery.

If the Applicable Device's Current Firmware Version Is…	Follow These Upgrade Steps
Xerus 4.0.x, 4.1.x	» 4.2.0 » 4.3.10
Xerus 4.2.x, 4.3.x	» 4.3.10

Note: Do NOT downgrade your new Xerus-based product(s) to any prior Xerus Firmware release. A downgrade to ANY prior firmware release is NOT SUPPORTED.

Release Highlights

New Products & Accessories Now Supported

Issue ID	Description
85481	New SOMM variant 6-port alt-phase, 4k/5k, 125A PDU

Bug Fixes

Issue ID	Description
85569	Fixed communication error with SmartLock
86279	Fixed Event Log issue displaying unknown user from unknown host
86221	Fixed NTP server communication issue
86177	Fixed long response time for SNMP GET request
86095	Fixed Event Log issue no showing Outlet operation
86071	Fixed crash issue when creating an outlet group with a linked unit outlet
85963	Fixed SmartLock controller issue losing connection with handle
85749	Fixed wrong naming in GUI for selectable table columns
85748	Fixed wrong table title in GUI for mobile submenu pages
85686	Fixed issue with SRC-0800 not loading all sensor data into PowerIQ
85684	Fixed issue with SmartLock controller losing connection
85493	Fixed outlet issue after resetting inlet energy

Security Fixes & Updates

Issue ID	Description
86285	Addressed CVE-2025-37973 – Wi-Fi: cfg80211: Fix out-of-bounds access during multi-link element defragmentation
85673	Updated OpenSSL to 3.0.16 (CVE-2024-13176)

Contact Us

Go to servertech.com/support for contact options.